

During our inspection time we observed that most of the Items are rusted and are in Skeleton condition / Scrap. The Induction Heater, Drilling Machine, Transformer, Melting Pot, Welding Transformer, etc., became scrap condition. The Furniture Items are in damaged condition. Most of the Machine Parts are in Dismantled / Damaged condition. Hence we value these items on "AS IS WHERE IS CONDITION" as hereunder.

### PARTICULARS OF THE MOVABLE ITEMS

SL No.	Description	Quantity
--------	-------------	----------

- |    |   |  |
|----|---|--|
| 1. | Induction Heater ( 1 No.), Drilling Machine (1 No.), Transformer ( 2 Units ), Welding Transformer ( 1 No.), Vacuum Tester (1 No.), Melting Pot (1 No.). All the above items are in Skeleton / Rusted condition. |  |
|----|---|--|

**Estimated Present Value of the above item on "As is where is condition".**

- |    |             |        |
|----|-------------|--------|
| 2. | Compressors | 2 Nos. |
|----|-------------|--------|

Condition : Poor, No maintenance since long  
Valued : "As is where is condition"

- |    |              |        |
|----|--------------|--------|
| 3. | Transformers | 2 Nos. |
|----|--------------|--------|

Condition : Poor, Rusted / Damaged  
Valued : "As is where is condition"

DCS/23746/248F/2015/IBK-R/J

20-08-2015

4. *Valves & Fixtures ( 2 Nos.), Vacuum Tester, etc.,*

*Condition : Poor, Rusted, No Maintenance since long*

*Valued : "As is where is condition"*

5. *Cupboard (2 Nos.), Working Table (5 Nos.), Office Chairs (4 Nos.), Executive Table with Chair (1 No.), M.S. Racks (3 Nos.), Wooden Shelves, Trays (4 Nos.), Fire Extinguisher Cylinder (1 No.), Pipes & Other Scrap, etc.,*

*Valued : "As is where is condition"*